

2004

Learjet 40

☆ HIGHLIGHTS

Interior refurbishment 2021 Very low hours

Exterior refurbishment 2020 Always hangered

Engines on JSSI ADSB-OUT / WAAS / LPV

SAIRFRAME

Total hours 4,374

MAINTENANCE

Engines JSSI

Maintenance Tracking CAMP

® ENGINES

2x Honeywell TFE 731-20 Engine 1 Engine 2
Total hours 4,374 4,374

MAVIONICS

Air Data Computer

Weather Radar Antenna

TCAS Processor

Radio Altimeter

VHF NAV

Integrated Avionics Computer

VHF

ELT

EGPWS

CVR

Radio Management Unit

FDR

Marker Beacon

ADS-B / WAAS / LPV

Honeywell AZ-950 Standby Compass

Honeywell WC-660

Honeywell RT-951

Honeywell RT-300 / AeroSonic

Honeywell RNZ-851

Honeywell IC-600

Honeywell RCZ-833M

Artex C406-2

Honeywell Mark V

Honeywell SSCVR

Honeywell RMU- 855

L3 Harris FA2100

Honeywell



2004

Learjet 40

INTERIOR

Interior refurbished 2021 to a very high standard

Oyster cream leather seats with diamond stitched panels

Oyster cream leather side-panelling

Luxury wool taupe carpet

Charcoal grey gloss cabinetry

Brushed aluminium fittings

♣ EXTERIOR

White paint with Silver and Navy-blue lines

☼ LOOSE EQUIPMENT

Portable Oxygen Cylinder

Engine Covers

Crew Passenger & Infant Life Vests

Pilot & Co-Pilot Portable Fire

Extinguisher

Pitot Covers

First Aid Kit

Cabin Portable Fire Extinguishers

Cabin seating for 6 in a centre club configuration of 4 with 2 forward

facing seats


Forward ref reshment centre

Four executive tables

Toilet with a solid door and a seat belt as #7 seat

DVD Player

La COLOUR PALLET




2004


Learjet 40













LET'S CONNECT

Whether you're looking to buy, lease, charter, or simply have a question we're here to help. Reach out to The Plane Factory and a member of our team will get back to you promptly.



team@theplanefactory.com



www.theplanefactory.com
f @ in @theplanefactory



